



GARY R. HERBERT
Governor

SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil Gas and Mining

JOHN R. BAZA
Division Director

7383

Page 1 of 2

Minerals Inspection Report

Reviewed

Report Date: 07/20/2016

Mine Name: Point of the Mountain (South Hansen)	Permit Number: M035/0026	Mine Status: Active
Operator Name: Geneva Rock Products	Inspection Date: 07/19/2016	Permit Fees: Paid
Inspector(s): Leslie Heppler	Inspection Time: 9:00 AM	Bond Amount: \$970,927
Attendee(s): Scott Thayn, Project Manager	Weather: Warm and dry	Bond Escalation: 09/01/2014
Inspection Purpose: Routine inspection - Focused on county line		Prior Inspection: 05/01/2013

Conclusions and Recommendations


The focus of this inspection was area adjacent to the old radio tower and the county line. Discussed with Operator the difference between restoration and reclamation. In addition, discussed possible options on slope angles ranging from 1H:1V to 2H:1V for the area noted in the Division Directive dated December 23, 2015. The Division directive was written by Lynn Kunzler, edited by Paul Baker and signed by Mike Bradley.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Permit is past due for escalation, but Operator has been granted extensions. Additional bond money was submitted for 10 acres as was noted in bond memorandum by Paul Baker dated November 30, 2015. Additional disturbance was less than 10 acres.		
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Public access to the site is limited, there are no shafts on site and no trash noted on site.		
3. <i>Protection of Drainages/Erosion Control</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No off-site erosion was noted at the time of inspection.		
4. <i>Deleterious Material</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Fuel was stored in secondary containment (see attached photograph)		
5. <i>Roads (maintenance, surfacing, dust control, safety)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Roads were well maintained and water was used for dust suppression. In addition large diameter 8-12" water lines were installed for dust suppression of highwalls and stockpiles.		
6. <i>Reclamation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No reclamation has been started.		
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Highwall was in good condition and consistent with NOI.		
8. <i>Soils</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Soil stockpiles were not inspected during this site inspection		
9. <i>Revegetation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Re-vegetation was not reviewed during this site inspection		
10. <i>Other</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Reviewed the boundary area between the Staker Parsons sand and gravel operation (no permit required by rule) and the Point of the Mountain (South Hansen) permitted area. The area is being mined by Staker Parsons for sand and gravel as the slope angle for sand and gravel is less than 1H:1V.		


Inspector's Signature:

CC: Operator - bsumsion@clydeinc.com, Draper City - Russell.Fox@draper.ut.us


File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M035-SaltLake/M0350026-PointMtn/inspections/INSP-07192016.pdf



Area to be restored/reclaimed



Two 20,000 water tanks used for dust suppression



Dust suppression on stockpile



12" water line to the top of the hill